

Parish Flood List

74 Next
Number

75

#	Location	Where	Landowner / Responsibility	Issue/Impact (Jan 16)	Cause	Short Term Actions (by Feb 16)	Maintenance Required	More Action Needed	Steps Already Taken (Oct 16 Update)
16	Patterdale	Noran Bank Farm	Jackson Family	Trees in beck		Clear trees			Trees cleared.
17	Patterdale	Green Bank Farm	Iredale Family	Trees in beck		Clear trees			Trees cleared.
18	Patterdale	Road between Noran Bank and Greenbank	Highways	Landslip			Regular clearing of culvert and drain	Fill the holes and stabilise the bank	Landslip cleared, culvert cleared, new drains installed. Hole still needs to be filled at top of bank. Consider tree planting if on a rock bar
21	Patterdale	Beckstones	National Trust/Side Farm	Gravel in fields, debris in beck					Fields clear
19	Patterdale	upstream of Goldrill Bridge	Goldrill Cottage/Old Water View	Erosion of bank with potential to undermine wall and road	Trees in beck on Goldrill Cottage side causing water to flow into opposite beck bank	Remove trees from the beck on Goldrill cottage side.			Still trees in the beck altho bags of rock were put in at the beck edge under the railings in Sept 2016
20	Patterdale	Goldrill Bridge	Highways	Road surface broken up	Volume of water overflowing from Goldrill Beck	Clear trees and debris around bridge from Goldrill Cottage. Consider dredging of beck either side of the bridge		Consider "overflow" route through Goldrill cottage garden - so rather than rebuild the wall by the bridge build a fence instead to allow water through	Fence built
22	Patterdale	Crookabeck	Crookabeck	Gravel in fields, debris in beck					Fields clear
23	Patterdale	Path to Blowick	NT/LDNP	Path washed away					Path filled in with material from Jenkins Field
24	Patterdale	Side Farm by Goldrill Beck	National Trust/Side Farm	Fences down and gravel in fields	Goldrill Beck breach	Clear debris and reinstate fences. Consider dredge of Goldrill Beck			Goldrill beck below Goldrill Bridge dredged. Fields cleared behind White Lion

Parish Flood List

#	Location	Where	Landowner / Responsibility	Issue/Impact (Jan 16)	Cause	Short Term Actions (by Feb 16)	Maintenance Required	More Action Needed	Steps Already Taken (Oct 16 Update)
25	Patterdale	Place Fell	Dalemain Estate	2 major landslips causing mud/debris to cover road up to Rookings and into gardens of Place Fell Cottage, GreenRigg and Broad How. Also	Destabilisation of fell	Complete survey of landslips. Reinstate footbridge over path at the base of Place Fell. Clear debris from Broad How			Debris cleared, culvert cleared, Bridge repaired. Still need full analysis of landslip - consider tree planting on rock bar
26	Patterdale	Rookings	Various	Blocked culverts & drains caused flooding in Rooking Cottage and washed road surface to Crookabeck	Blocked culverts/drains and volume of water		Clear Culverts.		Culverts cleared. New drain installed in front of Wordsworth cottage
66	Patterdale	Rookings	Various	Several overflows and flow diversions depositing many tons of stones/gravel across properties, ground erosion and some water ingress to	Build up of stones, blockages and force of water flow.		Continue to keep Ghyll clear.	Increase capacity where necessary, consider relief channels.	Ghyll bed and culverts cleared of debris. Consider leaky dams on fellside and gravel traps above houses to reduce flow and debris through houses
27	Patterdale	Between White Lion and Goldrill Bridge	Highways	Significant flooding on the road	Blocked culverts/drains and volume of water		Regular clearing of drain		Drain cleared
28	Patterdale	In front of Patterdale Hotel	Highways	Road flooding due to volume of water	Volume of water from behind Patterdale Hotel			Consider further clearance of becks around Mill Moss	Some minor dredging behind the hotel complete. Still to put in place a new drainage hole in the wall opposite the hotel and sort Mill
74	Patterdale	Patterdale School	Patterdale School	Flood damage under floors - new hall floor required#	Water from Goldrill beck			Replace Hall Floor	Floor replaced
29	Patterdale	Home Farm	Patterdale Hall Estate	Overflow of beck leading to debris into	Volume of water and capacity issue in beck				Beck dredged and bank built up
30	Patterdale	Church Corner	Various	Road flooded, flooding to Church, Rectory and Decollage	Blocked culverts/drains and volume of water	Clear culvert all the way to the road from Grisedale Beck	Clear Culverts.		Culverts cleared in the field but still concerns about their capacity.

Parish Flood List

#	Location	Where	Landowner / Responsibility	Issue/Impact (Jan 16)	Cause	Short Term Actions (by Feb 16)	Maintenance Required	More Action Needed	Steps Already Taken (Oct 16 Update)
39	Glenridding & Patterdale	A592 between Glenridding and Patterdale	Highways	Lake overflow onto the road leading to road closure for 2 days	Volume of water in the lake				Debris cleared from the lake. Still a blocked drain by Patterdale Hall