

1. Hartsop – Horsemans Bridge



High given level of rain

2. Hartsop - Cow Bridge



Very high given level of rain

3. Hartsop – Packhorse Bridge



Good clearance as always...

4. A592 North of CowBridge



Road surface water – blocked drain....

5 – 1 Lanefoot Cottages



Highways need to sort this as requested – resident needs sandbags in place every time it rains due to poor finish to road resurfacing earlier in the year

6 – Back of Lanefoot Cottages



Holding up well

7 – Manor Barn Bridge



Holding up well

8 – Goldrill Bridge looking north



Major problem area given so little rain

9 - Goldrill Bridge looking south (Goldrill Cottage garden)



Major problem area given so little rain

10 – Back of Patterdale School



Major problem area given so little rain

11 – Grisedale Bridge



High given level of rain

12 – Rattlebeck Bridge Gillside Glenridding



Holding up well

13- Wallbank Glenridding



Holding up well

14 – Gillside Campsite works



Holding up well

15 – Glenridding Garage Drain Grill



Grill needs clearing Carl!

16 – Glenridding Beck Mouth



Holding up well thanks to low level of Ullswater

17 – Jenkins Field Ramp



Holding up well

18 – Glenridding Bridge downstream



Holding up well

19 – Glenridding Bridge Upstream



Holding up well

20 – Glenridding Sewage Treatment Works



This would be my concern – would request inspection by EA

21 – Steamer Road



Water still pooling in the same place – once again suggest landscaping a run-off into Jenkins Field